[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-1253; Project Identifier MCAI-2022-00698-T]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Aerospace LP Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Gulfstream Aerospace LP Model Gulfstream G280 airplanes. This proposed AD was prompted by a determination that the existing wet runway performance tables in the airplane flight manual (AFM) may not provide an acceptable level of safety. This proposed AD would require revising the existing AFM to incorporate new wet runway performance tables, as specified in a Civil Aviation Authority of Israel (CAAI) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.
 - Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC

Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m.,
 Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact Civil Aviation Authority of Israel (CAAI), P.O. Box 1101, Golan Street, Airport City, 70100, Israel; telephone 972-3-9774665; fax 972-3-9774592; email aip@mot.gov.il. You may find this material on the CAAI website at caa.gov.il. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at regulations.gov by searching for and locating Docket No. FAA-2022-1253.

Examining the AD Docket

You may examine the AD docket at regulations.gov by searching for and locating Docket No. FAA-2022-1253; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above. **FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3225; email dan.rodina@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under ADDRESSES. Include "Docket No. FAA-2022-1253; Project Identifier MCAI-2022-00698-T" at the beginning of your comments. The most helpful comments reference a specific portion of the

proposal, explain the reason for any recommended change, and include supporting data.

The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dan Rodina,

Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3225; email dan.rodina@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The CAAI, which is the aviation authority for Israel, has issued CAAI AD ISR-I-97-2022-04-9, dated May 1, 2022 (CAAI AD ISR-I-97-2022-04-9) (also referred to as

the MCAI), to correct an unsafe condition for all Gulfstream Aerospace LP Model Gulfstream G280 airplanes.

This proposed AD was prompted by the determination that the existing wet runway performance tables in the AFM may not provide an acceptable level of safety, and that the wet runway performance tables have been updated in the Performance section of the G280 AFM, Revision 10. The FAA is proposing this AD to address the existing wet runway performance tables that could allow the airplane to experience runway excursions or overruns during takeoff. See the MCAI for additional background information.

Related Service Information under 1 CFR Part 51

CAAI AD ISR-I-97-2022-04-9 specifies procedures for updating the Performance section of the G280 AFM to incorporate new wet runway tables.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in this NPRM

This proposed AD would require accomplishing the actions specified in CAAI AD ISR-I-97-2022-04-9 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs.

The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate CAAI AD ISR-I-97-2022-04-9 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with CAAI AD ISR-I-97-2022-04-9 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Service information required by CAAI AD ISR-I-97-2022-04-9 for compliance will be available at regulations.gov by searching for and locating Docket No. FAA-2022-1253 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this proposed AD would affect 195 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

Estimated costs for required actions

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour X \$85 per hour = \$85	\$0	\$85	\$16,575

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress

charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Gulfstream Aerospace LP: Docket No. FAA-2022-1253; Project Identifier MCAI-2022-00698-T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Gulfstream Aerospace LP Model Gulfstream G280 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Unsafe Condition

This AD was prompted by a determination that the existing wet runway performance tables in the airplane flight manual (AFM) may not provide an acceptable level of safety. The FAA is proposing this AD to address the existing AFM wet runway performance tables that could allow the airplane to experience runway excursions or overruns during takeoff.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Civil Aviation Authority of Israel (CAAI) AD ISR-I-97-2022-04-9.

(h) Exception to CAAI AD ISR-I-97-2022-04-9

Where CAAI AD ISR-I-97-2022-04-9 refers to its effective date, this AD requires using the effective date of this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

- (1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.
- (2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or CAAI; or CAAI's authorized Designee. If approved by the CAAI Designee, the approval must include the Designee's authorized signature.

(j) Related Information

(1) For CAAI AD ISR-I-97-2022-04-9, contact Civil Aviation Authority of Israel (CAAI), P.O. Box 1101, Golan Street, Airport City, 70100, Israel; telephone 972-3-9774665; fax 972-3-9774592; email aip@mot.gov.il. You may find this CAAI AD on the CAAI website at caa.gov.il. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA.

For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket at regulations.gov by searching for and locating Docket No. FAA-2022-1253.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3225; email dan.rodina@faa.gov. Issued on September 29, 2022.

Christina Underwood, Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-21572 Filed: 10/4/2022 8:45 am; Publication Date: 10/5/2022]